

August 8, 2019

WE2.032 Rev. 1


Gunite Automatic Slack Adjusters

Subject: Engineering change to eliminate cotter pins

The Gunite automatic slack adjusters will undergo an engineering change to improve assembly and disassembly with the clevis body. The new design features pins with an integrated spring-loaded clip, as opposed to the cotter pin design that previously held the pins in place. The new pins snap in place with no additional operations and are removed by pushing in the spring-loaded clip and removing the pins.

Automatic Slack Adjusters Affected

Starting September 4, 2019, the SA10802 and SA10803 part numbers will be changed to the new pin. All other Gunite Slack Adjuster assemblies will be changed before the end of 2019. Service kits will retain the old cotter pin design until inventory is depleted. The new pin design is interchangeable with the old design in all applications.



Support

If you have any questions or concerns, please contact Field Engineering:

- (800) 869-2275
- Option #1 Warranty
- Option #3 Gunite Technical Services
- warrantyadmin@accuridecorp.com



(800) 626-7096 | accuridewheelendsolutions.com