



December 2, 2020

NO: WES2.039 Rev. 1

Gunite Front Hub Obsolescence

Part Numbers: HF861K, HF861K1, HF861K2

Effective immediately, Accuride Wheel End Solutions (AWES) will obsolete three Gunite front hub part numbers. These hubs will be in "Sell-Out Inventory" status until remaining part supply is exhausted, at which time the parts will be considered obsolete.

Your Accuride sales representative will be working with you to ensure a smooth transition.

Gunite P/N	Description	Special Notes
HF861K	Steer Axle Hub Assembly 5.06" offset SAE FF axle with 6 on 5.5" BC Hubcap	Move to "Sell-Out Inventory". No replacement parts available.
HF861K1	Steer Axle Hub Assembly 5.06" offset SAE FF axle with 6 on 5.5" BC Hubcap for steel wheels	Move to "Sell-Out Inventory". No replacement parts available.
HF861K2	Steer Axle Hub Assembly 5.06" offset SAE FF axle with 6 on 5.5" BC Hubcap for aluminum wheels	Move to "Sell-Out Inventory". No replacement parts available.

Thank you for your continued support of Accuride Wheel End Solutions. If you have any questions, please contact your Accuride sales representative.



ACCURIDE



GUNITE



(800) 626-7096 | accuridecorp.com