

Gunite Front Hub Obsolescence
Part Numbers: 900HF850K, 900HF850K1, 900HF850K2, 900HF851K

Effective immediately, Accuride Wheel End Solutions (AWES) will obsolete four Gunite front hub part numbers which will be replaced by the equivalent KIC designs. This change is the result of product synergy activities within AWES.

KIC brand hubs are well known in the market and perform well in the appropriate applications. The four Gunite part numbers will be listed as "Obsolete – limited inventory" until all existing inventory is exhausted.

Your Accuride sales representative will be working with you to ensure the replacement part numbers are communicated correctly along with pricing for a smooth transition.

Gunite P/N	Description	Special Notes
900HF850K	Steer Axle Hub Assembly	Move to Obsolete – limited inventory. Serviced by SVC-02540. Gunite studs W1164 (steel wheel) and W1327 (aluminum wheel) can be used in the KIC 02540 hub family. Stud standout will be increased, fit needs to be verified. Exciter (tone rings) are not cross compatible.
900HF850K1	Steer Axle Hub Assembly	Move to Obsolete – limited inventory. Serviced by HUB-02540.
900HF850K2	Steer Axle Hub Assembly	Move to Obsolete – limited inventory. Serviced by HUB-02540X.
900HF851K	Steer Axle Hub Assembly	Move to Obsolete – limited inventory. No direct replacement. Serviced by SVC-02540. Application must be converted to HP10 mount.

Thank you for your continued support of Accuride Wheel End Solutions. If you have any questions, please contact your Accuride sales representative.

